

Cactus RF60X Firmware Release Notes

Cactus Firmware Compatibility

| Firmware Generations | V6 II | V6 IIs | V6 | RF60 | RF60X |
|-------------------------|------------------------------|-------------------------|--------------------------|------|-------|
| Current "A" versions | V62.A.001 Multi-brand HSS | SON.A.004 Sony X-TTL | V61.A.003 Multi-brand | A.07 | A.08 |
| | CAN.A.004 Canon X-TTL | | | | |
| | FUJ.A.004 Fujifilm X-TTL | | | | |
| | NIK.A.005 Nikon X-TTL | | | | |
| | OLY.A.004 M43 X-TTL | | | | |
| | PEN.A.005 Pentax X-TTL | | | | |
| | SIG.A.004 Sigma X-TTL | | | | |
| Legacy versions | 1.1.013 Multi-brand HSS | SON.1.002 Sony X-TTL | 2.1.001 Multi-brand | 2.05 | 1.03 |

Same generation firmware for different devices is compatible with each other.

Firmware A.08 (Released on 24 Sep 2018)

Bug fixes:

- Fixed the occasional misfiring and incorrect power levels when working with V6 II and V6 IIs X-TTL firmware.

Firmware A.07 (Released on 25 May 2018)

X-TTL compatibility:

- Supports the Canon X-TTL firmware (firmware version prefix: CAN.A.xxx). Check

the updated table below about the compatible RF60X firmware versions for each V6 II and V6 IIS firmware:

Firmware A.06 (Released on 26 Mar 2018)

X-TTL compatibility:

- Supports the latest versions of the Sony, Fujifilm and Sigma X-TTL firmware (firmware version prefix: FUJ.A.xxx, SIG.A.xxx and SON.A.xxx).

Firmware A.05 (Released on 14 Mar 2018)

Bug fix:

- Fixed the inaccurate TTL exposure when adjusting EV value from -5 to +2 from V6 II TX with Fujifilm X-TTL.

Firmware A.04 (Released on 02 Mar 2018)

X-TTL compatibility:

- Supports Nikon X-TTL when working with the Nikon X-TTL firmware of the V6 II (firmware version prefix: NIK.A.xxx).

Firmware A.03 (Released on 27 Dec 2017)

Bug fix:

- Fixed the problem of the buzzer being activated mistakenly in <MULTI FLASH>.

Firmware A.02 (Released on 1 Dec 2017)

X-TTL compatibility:

- Supports Olympus / Panasonic (M43) X-TTL when working with the Olympus X-TTL firmware of the V6 II (firmware version prefix: OLY.A.xxx).

Bug fixes:

- Fixed the non-response of the <SLEEP> timer in A01.
- Fixed the inaccurate flash power when triggered from the V6 II X-TTL firmware in <FLASH COMPENSATE> mode at EV -3 or lower.

Firmware A.01 (Released on 7 Nov 2017)

X-TTL compatibility:

- Supports Pentax X-TTL when working with the Pentax X-TTL firmware of the V6 II (firmware version prefix: PEN.A.xxx).

Firmware 1.03 (Released on 16 Jun 2017)

New feature:

- Added wireless Multi Flash support in S mode when being commanded by the V6 II or V6 IIs TX with X-TTL firmware.

Flash power calibration:

- Improved the accuracy of TTL exposure in S mode when being commanded by the V6 II or V6 IIs TX with X-TTL firmware.

Firmware 1.02 (Released on 19 May 2017)

New feature:

- Added wireless TTL support in S mode for Sigma, Fujifilm and Sony when being commanded by the V6II or V6IIs TX unit with X-TTL firmware.

Bug fixes:

- Fixed the occasional unintended triggering in S mode.
- Fixed the incorrect display of 20mm zoom status in S mode. It was displayed when users configure one step below the minimum zoom of 24mm on the flash panel.
- Improved the accuracy of the battery status.